

# Product Safety Recall

## 215/60R16 95V SUPERCAT TYRE MADE IN THAILAND

The tyres affected are 215/60R16 95V Supercat, **made in Thailand**.

These tyres were imported by Bridgestone Australia Ltd and sold in Australia between 1<sup>st</sup> May 2010 to 8<sup>th</sup> Feb 2016 through Bridgestone Select, Bridgestone Service Centres and Bridgestone Tyre Centres.



### Defect

Bridgestone has detected that some of these tyres may exhibit an issue with the tread / belt leading to possible rapid loss of air pressure.

### Hazard

If the defect occurs, there may be loss of vehicle control which may pose a hazard to the driver and/or other road users.

### What to do

If you believe you have an affected tyre, please either call toll free number **1800 354 864** or email [customerservice@bridgestone.com.au](mailto:customerservice@bridgestone.com.au) to arrange a replacement of the affected tyres. The affected tyres will be replaced free of charge.

Further information can be obtained on the internet site [www.bridgestonetyres.com.au](http://www.bridgestonetyres.com.au).

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information**